

SMBQS18YL	SMBQS30L	SMBQS30LT	SMBQS30Y
<p>All measurements in mm</p>	<p>All measurements in mm</p>	<p>All measurements in mm</p>	<p>All measurements in mm</p>
<p>Hole size: <b>A</b> = <math>\varnothing</math> 15.3</p>	<p>Hole center spacing: <b>A</b> to <b>B</b> = 35                      Hole size: <b>A</b> = <math>\varnothing</math> 4.3, <b>B</b> = 4.25 x 16.3</p>	<p>Hole center spacing: <b>A</b> to <b>B</b> = 35                      Hole size: <b>A</b> = <math>\varnothing</math> 4.3, <b>B</b> = 4.25 x 16.3</p>	<p>Hole size: <b>A</b> = <math>\varnothing</math> 15.3</p>
<ul style="list-style-type: none"> <li>• Heavy-duty die-cast bracket for industrial protection</li> <li>• Replaceable window</li> <li>• M18 vertical mount-option</li> <li>• Nut and lock washer included</li> </ul>	<ul style="list-style-type: none"> <li>• Right-angle bracket for cable sensor models</li> <li>• Clearance for M4 (#8) hardware</li> <li>• <math>\pm</math> 12° tilt adjustment</li> <li>• 14-ga. stainless steel</li> </ul>	<ul style="list-style-type: none"> <li>• Tall right-angle bracket for QD models</li> <li>• <math>\pm</math> 8° tilt adjustment</li> <li>• 14-ga. stainless steel</li> </ul>	<ul style="list-style-type: none"> <li>• Heavy-duty die-cast bracket</li> <li>• M18 vertical mount option</li> <li>• <math>\pm</math> 8° tilt adjustment with cabled units</li> <li>• Includes nuts and lock washer</li> </ul>
Side Mount	Side Mount	Side Mount	Side Mount
<p>Used with</p>	<p>Used with</p>	<p>Used with</p>	<p>Used with</p>
<p>QS18AF (Class 2 Laser Only)</p>	<p>QS30</p>	<p>QS30 with integral QDs</p>	<p>QS30 (DC only)</p>

- Accessories
- Brackets
- Cordsets
- Retroreflectors
- Miscellaneous
- Reference

More on next page