

# Product data sheet

## Characteristics

# S33875

## CB ROTARY HANDLE REPLACEMENT KIT

Product availability: Non-Stock - Not normally stocked in distribution facility

Price\*: 795.00 USD

### Main

|                   |                |
|-------------------|----------------|
| Commercial Status | Commercialised |
|-------------------|----------------|

### Ordering and shipping details

|                       |   |
|-----------------------|---|
| Category              | 01250 - M,P,R FRAME ACCESSORIES ONLY                      |
| Discount Schedule     | DE2   |
| GTIN                  | 00785901821250  |
| Nbr. of units in pkg. | 1   |
| Product availability  | Non-Stock - Not normally stocked in distribution facility |
| Returnability         | N   |
| Country of origin     | US  |

### Offer Sustainability

|                          |                           |
|--------------------------|---------------------------|
| Sustainable offer status | Not Green Premium product |
|--------------------------|---------------------------|

### Contractual warranty

|                 |           |
|-----------------|-----------|
| Warranty period | 18 months |
|-----------------|-----------|

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric Industries SAS nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein. \*Prices are indicative